

Technical Bulletin



Condition

Replacing Comfort System Central Control Module -J393-

Follow this procedure when the Comfort System Central Control Module -J393- is being replaced for any reason.

97 06 02 4/28/2006, 2011776/1

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Passat	2006	All	All	All	All

Technical Background

The Electronic Steering Column Lock Control Module -J764-, attached to the steering column, with index level D can only be adapted to the Anti-Theft Immobilizer Control Module -J362- once.

Production Solution

No Change

Service



Tip:

The part number of the Electronic Steering Column Lock Control Module -J764- can be viewed electronically at the first screen when entering diagnostic address 25. This should be done with the original Comfort System Central Control Module -J393- installed and is only possible with successful communication.

When replacing the Comfort System Central Control Module -J393- observe the index level of the Electronic Steering Column Lock Control Module -J764-.

If the index level of the Electronic Steering Column Lock Control Module -J764- is indexed at D:

- Replace the Electronic Steering Column Lock Control Module -J764- .
- See (Repair Manual, Suspension, Wheels, Steering, Repair Group 48) for replacement procedures.

If the index level of the Electronic Steering Column Lock Control Module -J764- is indexed at any other level:

- DO NOT replace the Electronic Steering Column Lock Control Module -J764-.

Additional Information

Refer to Repair Manual for additional information regarding the Anti-theft Immobilizer 4 system.